

DALI

DG/S x.64.1.1: Why does the i-bus tool show a conflict on page "General"?

There may be two reasons for this:

- Device configuration does not match the DALI system configuration
- Ballasts that are not parametrized as individual ballasts must be fully assigned to the groups

Unique solution ID: #1615

Author: BA Engineering Team

Last update: 2024-10-29 08:43