

Heating, Ventilation and Air Conditioning

Why does the air quality sensor LGS/A 1.2 do not have a standard KNX bus connector?

The standard bus connection terminal would have increased the depth of the housing which was no option for this device.

Unique solution ID: #1519

Author: Carolina Bachenheimer-Schaefer

Last update: 2017-12-05 13:31