

Movement and Presence Detection

How can I connect my smart device with the Busch-Watchdog PRO KNX when I am missing the first 30 minutes after powering it on?

If 30 minutes have passed and you haven't yet connected to the device via Bluetooth, but you now want to connect, simply power off the device, wait 5 seconds, and then power it on again. This will reset the 30-minute window.

Unique solution ID: #1785

Author: BA Engineering Team

Last update: 2025-06-06 13:41