## **DALI**

## Can overlapping groups be implemented with the DALI Light Controller?

This function of overlapping groups is not implemented in the DALI Light Controllers. If overlapping groups are used on the DALI side anyway, then parameterized functions can no longer be ensured.

With help from the ABB i-bus Tool, overlapping groups can be shown as an indication, but not produced themselves.

Unique solution ID: #1226 Author: BA Engineering Team Last update: 2024-10-29 08:41