Heating, Ventilation and Air Conditioning FCC/S 1.x.x.1: What should be considered if weighting of internal and external measurement is set to 0%?

If all measurements are set to 0% only one value is used for calculation. The following examples shows which one:

Internal measurement weighting	0	counts 100%	÷	%
Weighting of external measurement 1	0		÷	%
Weighting of external measurement 2	0		*	%
Weighting of external measurement 1	0	counts 100%	÷	%
Weighting of external measurement 2	0		÷	%

Unique solution ID: #1584 Author: Marcel Feuerstein Last update: 2018-07-04 15:00